Inspection Report

Name of Work	:	Improvements to footpath & Drains in 16th & 19th Cross road & Other Roads in Ward No.13, Shettyhalli Sub Division
Work Order	:	No. EE/DD/WO/217/13-14, Dated: 27.01.2014.
Agency	:	B T Ravikumar
B.R. No & Dated	:	541/14-15, Date:30.08.2014
Bill Amount	:	1415054/-
Job Code	:	013-14-000006
P. Code	:	P-1771

Date of Inspection :- 06-03-16

The above said work Improvements to footpath and drains in 16th & 19th Cross road & other Roads in Ward No 13 Shettyhalli Sub Div. was shown to me by the Concerned A.E.

The above said work was inspected by me along with the Concerned AE Shri Nagbushan.

The work done is satisfactory

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರಾಜಾಜಿನಗರ, ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ದಾಸರಹಳ್ಳಿ ವಲಯ, ಬೆಂಗಳೂರು

Scanned by CamScanner